



Autotop — vehicle inspection report

Report #26 — 13 Jun 2026

Vehicle & customer

Customer	ryuryu
Email	twndsanjeewa@gmail.com
Registration	rthtrh
VIN	ryry
Make / Model	hrytr yt
Year	2026
Odometer	45,555 km
Engine no.	uyyru
Transmission	uyu
Fuel	ghj
Inspector	ghjhgj

Inspection checklist

Exterior & Body		
Check item	Status	Notes / details
Paint condition	Good	—
Panel alignment	Good	—
Accident repair signs	Good	—
Rust	Good	—
Glass condition	Good	—
Lights	Good	—
Wipers	Good	—
Mirrors	Good	—

Interior		
Check item	Status	Notes / details
Seats	Good	—
Seat belts	Good	—
Warning lights	Good	—
Cluster	Good	—

Check item	Status	Notes / details
HVAC	Good	—
Infotainment	Good	—
Windows/locks	Good	—
Remote key	Good	—
Water damage signs	Good	—

Engine Bay

Check item	Status	Notes / details
Oil condition	Good	—
Coolant	Good	—
Brake fluid	Good	—
Transmission fluid	Good	—
Battery	Good	—
Leaks	Good	—
Belts	Good	—
Mounts	Good	—

Engine Performance

Check item	Status	Notes / details
Cold start	Good	—
Idle	Good	—
Noise	Good	—
Exhaust smoke	Good	—
Acceleration	Good	—
Vibration	Good	—

Diagnostics

Check item	Status	Notes / details
Full scan	Good	—
Fault codes	Good	—
Pending codes	Good	—

Check item	Status	Notes / details
Live data	Good	—
Readiness	Good	—
ECU issues	Good	—

Transmission

Check item	Status	Notes / details
Shift quality	Good	—
Delay/shock	Good	—
Clutch	Good	—
Driveshaft	Good	—
AWD/4WD	Good	—

Suspension & Steering

Check item	Status	Notes / details
Shocks	Good	—
Springs	Good	—
Bushings	Good	—
Ball joints	Good	—
Wheel bearings	Good	—
Steering rack	Good	—

Brakes

Check item	Status	Notes / details
Pads	Good	—
Rotors	Good	—
Fluid	Good	—
Hoses	Good	—
Handbrake	Good	—
ABS	Good	—

Tyres & Wheels

Check item	Status	Notes / details
------------	--------	-----------------

Tread depth	Good	—
Wear pattern	Good	—
Tyre age	Good	—
Spare	Good	—
Rims	Good	—
Alignment	Good	—

Undercarriage

Check item	Status	Notes / details
Leaks	Good	—
Rust	Good	—
Exhaust	Good	—
Chassis	Good	—
Subframe	Good	—

Electrical

Check item	Status	Notes / details
Battery test	Good	—
Alternator	Good	—
Starter	Good	—
Lights	Good	—
Sensors	Good	—

Road Test

Check item	Status	Notes / details
Engine load	Good	—
Transmission	Good	—
Steering	Good	—
Braking	Good	—
Noise	Good	—
Vibration	Good	—

Hybrid/EV

Check item	Status	Notes / details
Battery health	Good	—
Cooling system	Good	—
Inverter	Good	—
Charging	Good	—
Warnings	Good	—

Compliance

Check item	Status	Notes / details
WOF items	Good	—
Airbags	Good	—
Seatbelts	Good	—
Recalls	Good	—

Final Assessment

Check item	Status	Notes / details
Overall condition	Good	—
Repairs required	Good	—
Estimated cost	—	No amount recorded
Recommendation	—	No recommendation recorded